

EXHIBIT “F”

AST-27
REV. 1191

STAR 2 5 2005

Fatality

ALABAMA UNIFORM TRAFFIC ACCIDENT REPORT

DPS

ACKNOWLEDGMENTS

Accident No

Sheet 1 of 4

Microfilm No.

Local Case No:


Form 100-100 (Rev. 1-80) - Mississippi Department of Transportation. Includes sections for Driver Information, Vehicle Information, Accident Details, and Circumstances. Form is filled out for a crash involving Michael Duke and Gerald Ruhnow.

SEATING	Other Involved Unit (Circle One)										Other Involved Unit (Circle One)										CODES																																																																														
	<div style="display: flex; justify-content: space-between;"> <div>Unit 1 1 24 2 3 4 5 6 7 8 9</div> <div>10 11</div> </div> <div style="display: flex; justify-content: space-between;"> <div>12 - Pedestrian 13 - Rider of Domestic Animal 14 - Occ. of Non-Motorized Vehicle 15 - Victim of Other Circumstance/ Codes Not Applicable</div> <div>Other Involved Safety Equipment</div> </div>										<div style="display: flex; justify-content: space-between;"> <div>Unit 2 1 24 2 3 4 5 6 7 8 9</div> <div>10 11</div> </div> <div style="display: flex; justify-content: space-between;"> <div>12 - Pedestrian 13 - Rider of Domestic Animal 14 - Occ. of Non-Motorized Vehicle 15 - Victim of Other Circumstance/ Codes Not Applicable</div> <div>Other Involved Safety Equipment</div> </div>										SAFETY EQUIPMENT 01 - None Installed 02 - Not Applicable 03 - Unknown (Any Type) Lap Belt Only 11 - Fastened 12 - Not Fastened Lap/Shoulder Harness 21 - Lap Only Used 22 - Neither Used 23 - Shoulder Only Used 24 - Both Used Motorcycle Helmet 31 - None Used 32 - Used Air Bags 41 - Deployed, Belts Used 42 - Not Deployed, Belts Used 43 - Deployed, Belts Not Used 44 - Not Deployed, Belts Not Used Child Restraint 81 - Child Restraint Used 82 - Other Restraint Used 83 - None Used Pedal Cycle/Pedestrian 91 - Contrasting Clothing 92 - Non-contrasting Clothing																																																																														
VICTIMS	Name: Michael Duke Address: 467 Longview Road Pontotoc, Ms Unit No: 1 Seat Pos: 1 Injury Type: K Age: 36 Sex: M Ejection: N First Aid By: A Taken To: Troy Regional Medical Center Taken By: Haynes Ambulance										Name: Gerald Rubnow Address: 9655 N 1400 Avenue Osco, Il Unit No: 2 Seat Pos: 1 Injury Type: A Age: 55 Sex: M Ejection: N First Aid By: A Taken To: Troy Regional Medical Center Taken By: Haynes Ambulance																																																																																								
	INJURY TYPE K Killed B Bruise/Abrasion/Swelling A - Visible or Carried Non-Scene C - Not Visible - Has Pain/Faint										First Aid By M - Paramedic O - Other P - Police U - Unknown N - None																																																																																								
NARRATIVE AND DIAGRAM <p>Officer's Opinion of What Happened: Unit#2 was traveling north on U.S. 231. Unit#1 was traveling south on U.S. 231. A motorcycle from a previous accident that had just occurred was lying in the southbound lane of U.S. 231. Unit#1 topped the hill and struck the motorcycle lying in the roadway. The motorcycle lodged underneath Unit#1 causing the fuel tanks to rupture and explode. Driver of Unit#1 lost control of vehicle and started to travel into the northbound lane. Unit#2 crested the hill traveling north and struck Unit#1 which had just crossed into his lane of travel. Another explosion occurred engulfing both Units in flames.</p>																																																																																																			
ROADWAY ENVIRONMENT	For Each Roadway Environment Field, Circle One Entry for Each Involved Unit:																																																																																																		
	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>Unit 1 1</td> <td>Contributing Road Defects 1 1 - Shoulders Low 2 2 - Shoulders High 3 3 - Holes, Bumps, Etc. 8 8 - Other</td> <td>Surface Construction 1 1 - Asphalt 2 2 - Concrete 3 3 - Brick 4 4 - Unpaved 8 8 - Other</td> <td>Condition 1 1 - Dry 2 2 - Wet 3 3 - Icy 4 4 - Snowy/Slushy 5 5 - Muddy 8 8 - Other</td> <td>Accident In Or Related To Road Construction Zone? Yes Yes No No</td> <td>Material In Roadway (Contributing) 1 1 - None 2 2 - Rocks 3 3 - Trees/Limbs 4 4 - Dirt 5 5 - Gravel 6 6 - Oil/Petrol 8 8 - Other</td> <td>Material Source 1 1 - Not Applicable 2 2 - Natural Environment 3 3 - Dropped From Vehicle 4 4 - Already in Road, But Fell From Vehicle 8 8 - Other 9 9 - Unknown</td> <td>Character 1 1 - Straight-Level 2 2 - Straight-Down Grade 3 3 - Straight-Up Grade 4 4 - Straight-Hillcrest 5 5 - Curve-Level 6 6 - Curve-Down Grade 7 7 - Curve-Up Grade 8 8 - Curve-Hillcrest</td> </tr> </table>																				Unit 1 1	Contributing Road Defects 1 1 - Shoulders Low 2 2 - Shoulders High 3 3 - Holes, Bumps, Etc. 8 8 - Other	Surface Construction 1 1 - Asphalt 2 2 - Concrete 3 3 - Brick 4 4 - Unpaved 8 8 - Other	Condition 1 1 - Dry 2 2 - Wet 3 3 - Icy 4 4 - Snowy/Slushy 5 5 - Muddy 8 8 - Other	Accident In Or Related To Road Construction Zone? Yes Yes No No	Material In Roadway (Contributing) 1 1 - None 2 2 - Rocks 3 3 - Trees/Limbs 4 4 - Dirt 5 5 - Gravel 6 6 - Oil/Petrol 8 8 - Other	Material Source 1 1 - Not Applicable 2 2 - Natural Environment 3 3 - Dropped From Vehicle 4 4 - Already in Road, But Fell From Vehicle 8 8 - Other 9 9 - Unknown	Character 1 1 - Straight-Level 2 2 - Straight-Down Grade 3 3 - Straight-Up Grade 4 4 - Straight-Hillcrest 5 5 - Curve-Level 6 6 - Curve-Down Grade 7 7 - Curve-Up Grade 8 8 - Curve-Hillcrest																																																																							
Unit 1 1	Contributing Road Defects 1 1 - Shoulders Low 2 2 - Shoulders High 3 3 - Holes, Bumps, Etc. 8 8 - Other	Surface Construction 1 1 - Asphalt 2 2 - Concrete 3 3 - Brick 4 4 - Unpaved 8 8 - Other	Condition 1 1 - Dry 2 2 - Wet 3 3 - Icy 4 4 - Snowy/Slushy 5 5 - Muddy 8 8 - Other	Accident In Or Related To Road Construction Zone? Yes Yes No No	Material In Roadway (Contributing) 1 1 - None 2 2 - Rocks 3 3 - Trees/Limbs 4 4 - Dirt 5 5 - Gravel 6 6 - Oil/Petrol 8 8 - Other	Material Source 1 1 - Not Applicable 2 2 - Natural Environment 3 3 - Dropped From Vehicle 4 4 - Already in Road, But Fell From Vehicle 8 8 - Other 9 9 - Unknown	Character 1 1 - Straight-Level 2 2 - Straight-Down Grade 3 3 - Straight-Up Grade 4 4 - Straight-Hillcrest 5 5 - Curve-Level 6 6 - Curve-Down Grade 7 7 - Curve-Up Grade 8 8 - Curve-Hillcrest																																																																																												
INVESTIGATION	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td colspan="4"> Vision Obscured By: 1 1 - Buildings 2 2 - Signboards 3 3 - Trees, Crops, Bushes 4 4 - Blowing Snow/Sand 5 5 - Hillcrest 6 6 - Curve in Road 7 7 - Fog 8 8 - Parked Vehicle 9 9 - Moving Vehicle(s) 10 10 - Blinded by Sunlight 11 11 - Fire/Smoke 12 12 - Dust 13 13 - Blinded by Headlights 14 14 - Embankment 15 15 - Rain on Windshield 16 16 - Snow on Windshield 98 98 - Other 99 99 - Unknown </td> <td colspan="4"> Traffic Control 1 1 - Police Officer 2 2 - R.R. Crossing Gates 3 3 - R.R. Flashing Lights 4 4 - R.R. Cross Buck/Pave Mark 5 5 - Pedestrian Control 6 6 - Traffic Signal 7 7 - Flashing Beacon 8 8 - Stop Sign 9 9 - Yield Sign 10 10 - Lane Control Device 11 11 - Flagger 12 12 - No Passing Zone 97 97 - None 98 98 - Other </td> <td colspan="4"> Opposing Lanes Separated By: 97 97 - None 1 1 - Paved Surface 2 2 - Unpaved Surface 3 3 - Broken Painted Line 4 4 - Solid Painted Line 5 5 - Concrete Barrier 6 6 - Metal Guard Rail 7 7 - Fence 8 8 - Other Barrier 1 1 - One Lane 2 2 - Two Lanes 3 3 - Three Lanes 4 4 - Four Lanes 5 5 - Five Lanes 6 6 - Six Lanes or More </td> <td colspan="4"> Lanes 1 1 - One Lane 2 2 - Two Lanes 3 3 - Three Lanes 4 4 - Four Lanes 5 5 - Five Lanes 6 6 - Six Lanes or More </td> </tr> </table>																				Vision Obscured By: 1 1 - Buildings 2 2 - Signboards 3 3 - Trees, Crops, Bushes 4 4 - Blowing Snow/Sand 5 5 - Hillcrest 6 6 - Curve in Road 7 7 - Fog 8 8 - Parked Vehicle 9 9 - Moving Vehicle(s) 10 10 - Blinded by Sunlight 11 11 - Fire/Smoke 12 12 - Dust 13 13 - Blinded by Headlights 14 14 - Embankment 15 15 - Rain on Windshield 16 16 - Snow on Windshield 98 98 - Other 99 99 - Unknown				Traffic Control 1 1 - Police Officer 2 2 - R.R. Crossing Gates 3 3 - R.R. Flashing Lights 4 4 - R.R. Cross Buck/Pave Mark 5 5 - Pedestrian Control 6 6 - Traffic Signal 7 7 - Flashing Beacon 8 8 - Stop Sign 9 9 - Yield Sign 10 10 - Lane Control Device 11 11 - Flagger 12 12 - No Passing Zone 97 97 - None 98 98 - Other				Opposing Lanes Separated By: 97 97 - None 1 1 - Paved Surface 2 2 - Unpaved Surface 3 3 - Broken Painted Line 4 4 - Solid Painted Line 5 5 - Concrete Barrier 6 6 - Metal Guard Rail 7 7 - Fence 8 8 - Other Barrier 1 1 - One Lane 2 2 - Two Lanes 3 3 - Three Lanes 4 4 - Four Lanes 5 5 - Five Lanes 6 6 - Six Lanes or More				Lanes 1 1 - One Lane 2 2 - Two Lanes 3 3 - Three Lanes 4 4 - Four Lanes 5 5 - Five Lanes 6 6 - Six Lanes or More																																																																		
	Vision Obscured By: 1 1 - Buildings 2 2 - Signboards 3 3 - Trees, Crops, Bushes 4 4 - Blowing Snow/Sand 5 5 - Hillcrest 6 6 - Curve in Road 7 7 - Fog 8 8 - Parked Vehicle 9 9 - Moving Vehicle(s) 10 10 - Blinded by Sunlight 11 11 - Fire/Smoke 12 12 - Dust 13 13 - Blinded by Headlights 14 14 - Embankment 15 15 - Rain on Windshield 16 16 - Snow on Windshield 98 98 - Other 99 99 - Unknown				Traffic Control 1 1 - Police Officer 2 2 - R.R. Crossing Gates 3 3 - R.R. Flashing Lights 4 4 - R.R. Cross Buck/Pave Mark 5 5 - Pedestrian Control 6 6 - Traffic Signal 7 7 - Flashing Beacon 8 8 - Stop Sign 9 9 - Yield Sign 10 10 - Lane Control Device 11 11 - Flagger 12 12 - No Passing Zone 97 97 - None 98 98 - Other				Opposing Lanes Separated By: 97 97 - None 1 1 - Paved Surface 2 2 - Unpaved Surface 3 3 - Broken Painted Line 4 4 - Solid Painted Line 5 5 - Concrete Barrier 6 6 - Metal Guard Rail 7 7 - Fence 8 8 - Other Barrier 1 1 - One Lane 2 2 - Two Lanes 3 3 - Three Lanes 4 4 - Four Lanes 5 5 - Five Lanes 6 6 - Six Lanes or More				Lanes 1 1 - One Lane 2 2 - Two Lanes 3 3 - Three Lanes 4 4 - Four Lanes 5 5 - Five Lanes 6 6 - Six Lanes or More																																																																																						
<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td colspan="4"> Light 1 - Daylight 2 - Dawn 3 - Dusk 4 - Darkness-Road Not Lit 5 - Darkness-Road Lit </td> <td colspan="4"> Weather 1 - Clear 2 - Cloudy 3 - Rain 4 - Snow 5 - Sleet/Hail 6 - Crosswind 7 - Fog 8 - Other </td> <td colspan="4"> Locale 1 - Open Country 2 - Residential 3 - Shop or Business 4 - Mfg. or Industrial 5 - School 6 - Playground 8 - Other </td> <td colspan="4"> Non-Vehicular Property Damage 1 - None Visible 2 - Light 3 - Moderate 4 - Severe </td> <td colspan="4"> Properly Damage Description Description: N/A </td> </tr> <tr> <td colspan="4"> Time Police Notified AM/MT: 7 : 21 </td> <td colspan="4"> Time Police Arrived AM/MT: 8 : 26 </td> <td colspan="4"> Time EMS Arrived AM/MT: 7 : 31 </td> <td colspan="4"> Name of Photographer: Trp. Kevin D. Cook </td> <td colspan="4"> Owner: _____ Address: _____ </td> </tr> <tr> <td colspan="10"> Witness Full Name: Gene Richardson Address: 276-B Timber Ridge Drive Thomasville, Ga. Telephone: 229 226-3912 </td> <td colspan="10"> Witness Full Name: Randall Jackson Address: 630 W. Washington Street Orlando, Fl. Telephone: 407 841-1742 </td> </tr> <tr> <td colspan="10"> Name of Investigating Officer: Kevin D. Cook Officer ID: 833 Agency ORI: ALAST3800 Supervisor Reviewed: 54 </td> <td colspan="10"> Name of Other Investigating Officers at Scene: Jimmy Helms Officer ID: 753 Agency ORI: ALAST3800 </td> </tr> </table>																				Light 1 - Daylight 2 - Dawn 3 - Dusk 4 - Darkness-Road Not Lit 5 - Darkness-Road Lit				Weather 1 - Clear 2 - Cloudy 3 - Rain 4 - Snow 5 - Sleet/Hail 6 - Crosswind 7 - Fog 8 - Other				Locale 1 - Open Country 2 - Residential 3 - Shop or Business 4 - Mfg. or Industrial 5 - School 6 - Playground 8 - Other				Non-Vehicular Property Damage 1 - None Visible 2 - Light 3 - Moderate 4 - Severe				Properly Damage Description Description: N/A				Time Police Notified AM/MT: 7 : 21				Time Police Arrived AM/MT: 8 : 26				Time EMS Arrived AM/MT: 7 : 31				Name of Photographer: Trp. Kevin D. Cook				Owner: _____ Address: _____				Witness Full Name: Gene Richardson Address: 276-B Timber Ridge Drive Thomasville, Ga. Telephone: 229 226-3912										Witness Full Name: Randall Jackson Address: 630 W. Washington Street Orlando, Fl. Telephone: 407 841-1742										Name of Investigating Officer: Kevin D. Cook Officer ID: 833 Agency ORI: ALAST3800 Supervisor Reviewed: 54										Name of Other Investigating Officers at Scene: Jimmy Helms Officer ID: 753 Agency ORI: ALAST3800									
Light 1 - Daylight 2 - Dawn 3 - Dusk 4 - Darkness-Road Not Lit 5 - Darkness-Road Lit				Weather 1 - Clear 2 - Cloudy 3 - Rain 4 - Snow 5 - Sleet/Hail 6 - Crosswind 7 - Fog 8 - Other				Locale 1 - Open Country 2 - Residential 3 - Shop or Business 4 - Mfg. or Industrial 5 - School 6 - Playground 8 - Other				Non-Vehicular Property Damage 1 - None Visible 2 - Light 3 - Moderate 4 - Severe				Properly Damage Description Description: N/A																																																																																			
Time Police Notified AM/MT: 7 : 21				Time Police Arrived AM/MT: 8 : 26				Time EMS Arrived AM/MT: 7 : 31				Name of Photographer: Trp. Kevin D. Cook				Owner: _____ Address: _____																																																																																			
Witness Full Name: Gene Richardson Address: 276-B Timber Ridge Drive Thomasville, Ga. Telephone: 229 226-3912										Witness Full Name: Randall Jackson Address: 630 W. Washington Street Orlando, Fl. Telephone: 407 841-1742																																																																																									
Name of Investigating Officer: Kevin D. Cook Officer ID: 833 Agency ORI: ALAST3800 Supervisor Reviewed: 54										Name of Other Investigating Officers at Scene: Jimmy Helms Officer ID: 753 Agency ORI: ALAST3800																																																																																									
The data on this report reflects my best knowledge, opinions and beliefs covering the accident, but no warrant is made as to the factual accuracy thereof. Signature of Investigating Officer: Kevin D. Cook #833 Date: 7 Mar 2005																																																																																																			

SHEET 2 OF 4 SHEET(S)

SUPPLEMENTAL SHEET

ADDITIONAL ACCIDENT VICTIMS	
3	Name _____ Address _____ Taken to _____ Taken by _____
4	Name _____ Address _____ Taken to _____ Taken by _____
5	Name _____ Address _____ Taken to _____ Taken by _____
6	Name _____ Address _____ Taken to _____ Taken by _____
7	Name _____ Address _____ Taken to _____ Taken by _____
8	Name _____ Address _____ Taken to _____ Taken by _____
9	Name _____ Address _____ Taken to _____ Taken by _____
10	Name _____ Address _____ Taken to _____ Taken by _____
11	Name _____ Address _____ Taken to _____ Taken by _____
12	Name _____ Address _____ Taken to _____ Taken by _____
ADDITIONAL NARRATIVE SPACE	
DESCRIBE WHAT HAPPENED (Refer to vehicles by number)	
(SEE PAGE #1)	



U.S. 231

<u>Diagram Not to Scale</u> Diagram Scale 1 inch = (10 feet) / (20 feet)		Location U.S. 231 (Pike County)		Time 7:16	
Signature of Reporting Officer(s) <i>Kevin D. Cook</i>		Officer ID 833	Reporting Police Agency ORI ALAST3800	DATE Month 03 Day 07 Year 2005	